


Lake Forest Library



www.wje.com



February 15, 2022



Wiss, Janney, Elstner Associates, Inc.

Wiss, Janney, Elstner Associates, Inc.


Founded in 1956, Wiss, Janney, Elstner Associates, Inc., is a global firm of engineers, architects, and materials scientists committed to helping clients solve, repair, and avoid problems in the built world.





Disciplines

- Architecture
- Historic Preservation
- Structural Engineering and Testing
- Materials Science
- Geotechnical Engineering
- Fire Protection Engineering and Life Safety
- Metallurgical Engineering
- Other Disciplines






Services

- Historic Preservation
- Building Enclosure
- Building Science











Lake Forest Library Dome

Original construction 1930–1931



Photo by R O G Studio

The New Reed Memorial Library

View of the new Kersey Coates Reed Memorial library which is nearing completion on Deerpath, East, just east of the Methodist Episcopal church. The handsome building with its splendid equipment and rich furnishings is a gift to the city by Mrs. Reed and her sister, Mrs. Charles H. Schweppe. Its estimated cost is \$250,000.

Architect: Edwin H. Clark


General Contractor: H. F. Friestedt Co.

Sheet metal roofing: John W. Thompson Co.

March 1931



Changes over time





1930s

1950s-1960s Gutter added



Changes over time







1984 Dome Replacement









Changes over time






2017




Dome Assembly






Skylight











Skylight








Dome





United States Gypsum Company




SHEETROCK-PYROFILL ROOF CONSTRUCTION

General—Sheetrock-Pyrofill System of Roof construction consists of permanent Sheetrock forms and Pyrofill (Gypsum Fiber Concrete) reinforced with an electrically-welded, galvanized steel fabric supported on subpurlins clipped to the main structural steel purlins. It is sold only completely erected by the Contracting Division of the United States Gypsum Company.


Dome







Cornice







Cornice




1984






Corner Areas








Corner Areas



1984







Masonry






Drainage











Laylight








Circulation Room Ceiling







Murals







Next Steps

- Develop Schematic Concepts (in progress)
- Review by Library Board (March)
- Schematic Design and Pricing (April)
- Confirm scope and proceed to Construction Documents

